

ABSTRACT

Piezoelectric transformer with an input and an output region. Input and/or output regions are sub-divided into sections (13-16) of inverse polarization. Depending on the number of sections, a multiplication of the transformation ratio is achieved without increasing the field strength in the piezoelectric material.